

September 8, 2010: Gordon Stansberry Well Site and Pipeline - Photograph Log





	Photo ID: P1030232.JPG
	Date: 9/8/2010
	Description: Top of slope/valley fill Well pad visible in upper right-hand corner of photo

	Photo ID: P1030233.JPG
	Date: 9/8/2010
	Description: Middle of slope/valley fill


	Photo ID: P1030235.JPG
	Date: 9/8/2010
	Description: Bottom of slope/valley fill



Photo ID:

P9080201.JPG

Date:

9/8/2010

Description:

Photo of fill above
toe of slope



Photo ID:

P9080204.JPG

Date:

9/8/2010

Description:

Toe of slope; stream
fill



Photo ID:

P9080206.JPG

Date:

9/8/2010

Description:

Stream Channel;
Photo taken near
toe of the fill



Photo ID:

P9080207.JPG

Date:

9/8/2010

Description:

Debris in stream
channel



Photo ID:

P9080208.JPG

Date:

9/8/2010

Description:

Stream/culvert fill (~40 lf) discovered during inspection. Culvert visible in lower left-hand corner of photo



Photo ID:

P1030238.JPG

Date:

9/8/2010

Description:

Stream/culvert fill (~40 lf) discovered during inspection



	Photo ID: P1030240.JPG
	Date: 9/8/2010
	Description: Stream/culvert fill (~40 lf) discovered during inspection; View from above

	Photo ID: P9080219.JPG
	Date: 9/8/2010
	Description: Installation of pipeline above discovered stream fill

	Photo ID: P1030239.JPG
	Date: 9/8/2010
	Description: View of stream fill from above